



SMITHERS
QUALITY ASSESSMENTS

CERTIFICATE OF APPROVAL

This is to Certify that the Quality Management System of:

A. Raymond Tinnerman Automotive, Inc.

525 Mount Carmel Avenue

Flemingsburg, KY 41041

(Page 1 of 2; see Appendix)

has been assessed and approved by Smithers Quality Assessments, Inc., to the following quality management system standards and requirements:

ISO 9001:2008 with Design

The Quality Management System is Applicable to:

The design and manufacture of stamped and roll formed metals and injection molded plastic components and assemblies.

Approval
Certificate Number: 09.237.5

Original Approval: August 25, 2009

Current Certificate: September 17, 2015

Certificate Expires: September 14, 2018



The use of the accreditation mark indicates accreditation in respect of those activities covered by the above certificate number.

on behalf of SQA - J. Michael Hochschwender, CEO

The approval is subject to the company maintaining its system to the required standards which will be monitored by Smithers Quality Assessments, Inc., 121 S. Main St. Suite 300, Akron, Ohio 44308, USA



APPENDIX A
TO THE CERTIFICATE
OF REGISTRATION NO. 09.237.5



Page 2 of 2

SMITHERS QUALITY ASSESSMENTS, INC.

Site:

A. Raymond Tinnerman Automotive, Inc.
525 Mount Carmel Avenue
Flemingsburg, KY 41041
Scope of services provided by this location: Manufacturing

Supporting Locations:

A. Raymond Tinnerman Automotive, Inc.
3901 Research Drive
Rochester Hills, MI 48039
Scope of services provided by this supporting location: Contract review,
product design, engineering, sales, purchasing

A. Raymond Tinnerman Industrial, Inc.
1060 West 130th Street
Brunswick, OH 44212
Scope of services provided by this supporting location: Purchasing

Applicable Standard: ISO 9001:2008 with Design

This appendix applies only to those sites listed above. As other sites are assessed and approved, or as sites already approved are removed from active services, this appendix will be amended to show the current status. Sites not listed on this appendix shall not be viewed as approved.

